

2019 Hyundai Sonata Limited Seller's Stock#: Vin#:

\_\_\_\_\_

## **VEHICLE DETAILS**



VIN
Year
Make
Model
Exterior Color
Interior Color
Odometer
Transmission
Drivetrain
Engine
Number of Keys

2019 Hyundai Sonata Machine Gray Gray 4,068 Automatic Front Wheel 2.4L 4 One

### **GENERAL INFORMATION**

| MFR Model Code   | 284J2F4P          |
|------------------|-------------------|
| Body Type        | 4dr Car           |
| Pass Doors       | 4                 |
| Alternative Name |                   |
| Alternative Body | 4dr Car           |
| Drivetrain       | Front Wheel Drive |

**Original Pricing** 

| MSRP               | \$24,300.00 |
|--------------------|-------------|
| Invoice            | \$23,013.00 |
| Destination Charge | \$930.00    |

**Engine & Powertrain** 

| =0·····           |                              |
|-------------------|------------------------------|
| Туре              | 4 Cylinder Engine            |
| Displacement L/Cl | /                            |
| Fuel Type         | Gasoline Fuel                |
| Horsepower        | 185.0 @ 6000                 |
| Fuel Economy      | 25.0 City / 33.0 Highway MPG |



2019 Hyundai Sonata Limited Seller's Stock#: Vin#:

| Fuel Capacity | 18.0 gal     |
|---------------|--------------|
| Net Torque    | 178.0 @ 4000 |

### **Tech Specs**

| Manufactured By                    | United States Hyundai Passenger Cars |
|------------------------------------|--------------------------------------|
| Suspension Type - Front            | Strut                                |
| Suspension Type - Rear             | Multi-Link Multi-Link                |
| Front Tire Size                    | P215/55VR17                          |
| Rear Tire Size                     | P215/55VR17                          |
| Brake ABS System                   | 4-Wheel                              |
| Front Brake Rotor Diam x Thickness | 12.6, 12 in 12.0 min 12.6 max        |
| Rear Brake Rotor Diam x Thickness  | 11.2 in 11.2 min 11.2 max            |
| Wheelbase                          | 110.4 in 110.4 min 110.4 max         |
|                                    |                                      |

### **EQUIPMENT**

#### **Mechanical & Powertrain**

Engine: 2.4L GDI DOHC 16-Valve I4

Transmission: 6-Speed Automatic w/SHIFTRONIC -inc: OD lock-up torque converter and shift lock

Transmission w/Driver Selectable Mode

Front-Wheel Drive

2.89 Axle Ratio

80-Amp/Hr 640CCA Maintenance-Free Battery w/Run Down Protection

140 Amp Alternator

Gas-Pressurized Shock Absorbers

Front And Rear Anti-Roll Bars

**Electric Power-Assist Speed-Sensing Steering** 

18.5 Gal. Fuel Tank

Single Stainless Steel Exhaust w/Chrome Tailpipe Finisher

Strut Front Suspension w/Coil Springs

Multi-Link Rear Suspension w/Coil Springs

4-Wheel Disc Brakes w/4-Wheel ABS, Front Vented Discs, Brake Assist and Hill Hold Control

#### Interior

Heated Front Bucket Seats -inc: 10-way power driver's seat w/power lumbar support, 6-way manual passenger seat (height-adjustable) and passenger side seatback pockets

8-Way Driver Seat

**Passenger Seat** 

60-40 Folding Bench Front Facing Fold Forward Seatback Rear Seat

Manual Tilt/Telescoping Steering Column



2019 Hyundai Sonata Limited Seller's Stock#: | Vin#:

| Heated Leather Steering Wheel   |        |
|---|--------|
| Front Cupholder   |        |
|   |        |
|   |        |
|   |        |
| Rear Cupholder  |        |
| Valet Function  |        |
| Remote Releases -Inc: Smart Trunk Proximity Cargo Access and Power Fuel                         |        |
| Cruise Control w/Steering Wheel Controls  |        |
| Dual Zone Front Automatic Air Conditioning  |        |
| HVAC -inc: Underseat Ducts and Console Ducts  |        |
| Illuminated Locking Glove Box   |        |
| Driver Foot Rest  |        |
| Full Cloth Headliner  |        |
| Interior Trim -inc: Metal-Look Instrument Panel Insert, Metal-Look Door Panel Insert and Piano  |        |
| Black/Metal-Look Interior Accents   |        |
| Leatherette Door Trim Insert  |        |
| Leather/Metal-Look Gear Shifter Material  |        |
| Day-Night Rearview Mirror   |        |
| Driver And Passenger Visor Vanity Mirrors w/Driver And Passenger Illumination, Driver And Passe | enger  |
| Auxiliary Mirror  |        |
| Full Floor Console w/Covered Storage, Mini Overhead Console w/Storage and 2 12V DC Power Ou     | utlets |
| Front Map Lights  |        |
| Fade-To-Off Interior Lighting   |        |
| Full Carpet Floor Covering  |        |
| Carpet Floor Trim and Carpet Trunk Lid/Rear Cargo Door Trim                                     |        |
| Cargo Space Lights  |        |
| Blue Link Tracker System  |        |
| Driver / Passenger And Rear Door Bins   |        |
| Delayed Accessory Power   |        |
| Driver Information Center   |        |
| Redundant Digital Speedometer   |        |
| Outside Temp Gauge  |        |
| Analog Appearance   |        |
| Manual Adjustable Front Head Restraints and Fixed Rear Head Restraints                          |        |
| Front Center Armrest and Rear Center Armrest  |        |
| Perimeter Alarm   |        |
| Immobilizer   |        |
| Air Filtration  |        |
| 2 12V DC Power Outlets  |        |



2019 Hyundai Sonata Limited Seller's Stock#: Vin#:

#### **Exterior**

Wheels: 17 x 7.0J Aluminum Alloy

Tires: P215/55R17

Steel Spare Wheel

Compact Spare Tire Mounted Inside Under Cargo

**Clearcoat Paint** 

Body-Colored Front Bumper w/Chrome Bumper Insert

**Body-Colored Rear Bumper** 

Chrome Side Windows Trim and Black Front Windshield Trim

Chrome Door Handles

Body-Colored Power w/Tilt Down Heated Side Mirrors w/Manual Folding and Turn Signal Indicator

Fixed Rear Window w/Defroster

**Light Tinted Glass** 

Speed Sensitive Variable Intermittent Wipers

Fully Galvanized Steel Panels

Chrome Grille

Trunk Rear Cargo Access

Auto On/Off Projector Beam Halogen Daytime Running Headlamps w/Delay-Off

Perimeter/Approach Lights



#### **VEHICLE CONDITION**

**Exterior Condition:** Upon examination, the vehicle exhibits mainly cosmetic damage, most notably to the right-hand side. Scratches and dents are present on the front bumper, hood, and roof, suggesting exposure to external forces. The damage to the passenger side rear quarter panel is extensive and requires panel replacement rather than repair. Additionally, the passenger side mirror and rear quarter glass are compromised and need replacement. The damages are confined to the vehicle's exterior and are rectifiable with professional bodywork and component replacement.

**Interior Condition:** The vehicle's interior presents in good condition, reflecting responsible use and maintenance. The upholstery, including seats and carpeting, maintains a clean appearance with no significant wear or damage. Interior surfaces such as the dashboard, console, and door panels exhibit no major marks or blemishes. There are no pervasive odors or signs of harsh usage. All manual controls and fittings are intact and functional. The condition of the interior aligns with the expected standards for a vehicle of its age, mileage, and class, demonstrating a satisfactory level.

**Electrical Components:** A comprehensive testing of all electrical components has been conducted with positive results. The list of components verified includes, but is not limited to, the following:

- Headlights, Taillights, and Indicator Lights
- Instrument Cluster and Dashboard Illumination
- Power Windows and Central Locking System
- Multimedia System, Navigation, and Vehicle Information Interface
- Climate Control System
- Adjustable Seating and Mirrors
- All components are confirmed to be in full working order, functioning as intended by the manufacturer.

**Test Drive – Mechanical Assessment:** Due to the vehicle's salvage title status, conducting a full test drive to assess its mechanical operation under road conditions was not feasible. However, upon starting the vehicle, it was observed to run well and show no signs of damage to the engine. It was also confirmed that the vehicle is capable of moving under its own power within the confines of the current environment. These observations suggest that the primary mechanical components, including the engine, are functioning effectively.

In summary, the vehicle exhibits exterior cosmetic damage, notably on the right-hand side, with repairable scratches and dents, and a need for replacement parts on the passenger side. The interior is in good condition. All electrical components are functioning properly. Mechanically, the vehicle starts and runs well. Overall, the vehicle is well-maintained with manageable exterior repairs and a solid operational foundation.